

ALPHASET

TECHNOLOGICKÉ POSTUPY PRE TRANSFER A PRANIE

		STANDARDNÉ														POTLAČITELNÉ																					
		POLI-FLEX® PREMIUM		POLI-FLEX® BLOCKOUT		POLI-FLEX® NYLON		POLI-FLEX® STRETCH		POLI-FLEX® TURBO		POLI-FLEX® IMAGE REFLEX SILVER 4781 / REFLEX ECO 4782		POLI-FLEX® IMAGE BRILLANT 421 / 431		POLI-FLEX® PEARL GLITTER		POLI-FLEX® IMAGE PAINT / GLOSSY		TURBO PRINT 4036 MATT		ULTIMATE PRINT 4030 / 4032 MATT 4031 GLOSS		ULTIMATE PRINT MATT 4028		ULTIMATE PRINT SUPERSOFT 4033 MATT		POLI-FLEX® 4010 BLOCKOUT		POLI-FLEX® 4015 / 4016		POLI-FLEX® 4625 / 4626		SUBLI-FLOCK 5901 / TUBTHERM PES			
Transfer	Teplota (°C)	160	160	150	160	Standard 160 150 130	Nylon* 150	160	160	160	160	160	160	160	160	160	160	160	160	160	160	135	160	160	160	160	160	160	160	160	160	160	160	160	160	160	160
	Prítlak (bar)	2,5 - 3,0	2,5 - 3,0	2,0	2,5 - 3,0	2,5 - 3,0	2,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	2,5 - 3,0	
	Čas (sec.)	15	15	4	15	3 4 5	5+ 5+ 10*	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15
	Strhávajúce (za tepla – za studena)	W	W	W	W	W&C	W&C	W	C	W	W	W	W	C	W	W	W	W	W	W	W	W	C	C	W	C	W	C	W	W	W	W	W	W	W	W	
Pranie	Pranie do (°C)	80	60	40	80	60	40	60	iba ručne	60	60	60	40	60	60	40	80	60	40	40	40	40	40	40	60	90	60	60	60	60	60	60	60	60	60		
	Sušička	•			•	•**	•	•		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	
	Čistiareň	•	•		•	•				•																											

*POLI-FLEX® TURBO & TURBO PRINT
 1. 5 sekúnd predžehliť
 2. Prítlačiť na nylón - 5 sekúnd
 3. Po odňatí prenosky - 10 sekúnd

**POLI-FLEX® TURBO & TURBO PRINT
 použiť iba komerčné sušičky do 100 °C